**Observation Report**

| Report No |
|---|
| |

Donington AUCTIONS & SALES

| Auction Lot No |
|---|
| 8 |

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

| Inspection Date | Make/Model | Year | Odometer - Mls / Km | VIN |
|---|---|---|---|---|
| 23 November, 2026 | Goggomobil Dart | 1958 | 34499mi | Not sighted |

| EXTERIOR | Good | Fair | Repair | N/C | N/A | Comments |
|---|---|---|---|---|---|---|
| Presentation | ✔ | | | | | |
| Glass | | | | | | |
| Bodywork | ✔ | | | | | |
| Paintwork | | ✔ | | | | Some activity under paint observed in places |
| Lamps Condition | | ✔ | | | | Tail lights mis-matched |
| Bumper Bars | | | | | ✔ | |
| Brightwork | | ✔ | | | | |
| Seals | | | | | ✔ | |
| Convertible Roof | | | | | ✔ | No soft top |

| INTERIOR | Good | Fair | Repair | N/C | N/A | Comments |
|---|---|---|---|---|---|---|
| Boot Area | | | | | ✔ | |
| Seats & Belts | ✔ | | | | | |
| Floor Coverings | | ✔ | | | | |
| Headlining/Visors | | | | | ✔ | |
| Trim | | ✔ | | | | |
| Doors | | ✔ | | | | |
| Windows and Mirrors | | ✔ | | | | |
| Heating and Ventilation | | | | | ✔ | |
| Lights/Wipers/Washers/Horn | | | ✔ | | | Brake lights n/w, minor electrical gremlins |
| Other Electrical | | | ✔ | | | |
| Entertainment Equipment | | | | | ✔ | |
| ABS/SRS | | | | | ✔ | |

| UNDERBODY | Good | Fair | Repair | N/C | N/A | Comments |
|---|---|---|---|---|---|---|
| Structure | ✔ | | | | | |
| Corrosion | | ✔ | | | | |
| Powertrain | | ✔ | | | | |
| Exhaust | ✔ | | | | | |
| Brakes | | ✔ | | | | |
| Wheels & Tyres | | ✔ | | | | Tyres dated 47-14 |
| Steering & Suspension | | ✔ | | | | Play in steering shaft |
| Fuel System | | ✔ | | | | |
| Fluid Leaks | | | ✔ | | | Leaking master cylinder |



| ENGINE BAY | Good | Fair | Repair | N/C | N/A | Comments |
|---|---|---|---|---|---|---|
| Presentation | | ✔ | | | | |
| Fluid Levels/Condition | | ✔ | | | | |
| Cooling System | | ✔ | | | | |
| Power Steering | | | | | ✔ | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Electrical | | | ✔ | | | Battery n/s - needs strap |
| Engine Running | | ✔ | | | | |
| Air Conditioning | | | | | ✔ | |

| ROAD TEST | Good | Fair | Repair | N/C | N/A | Comments |
|---|---|---|---|---|---|---|
| Engine Performance | | ✔ | | | | |
| Transmission | | ✔ | | | | Linkage requires adjustment |
| Noise and Vibration | | ✔ | | | | |
| Steering and Suspension | | ✔ | | | | |
| Braking | | ✔ | | | | |
| Clutch | | ✔ | | | | |
| Instruments | | | ✔ | | | Speedo inoperable, horn missing |

## Key

| | | | |
|---|---|---|---|
| **Good** | Operational or well presented at time of inspection | **U/S** | Unservicable |
| **Fair** | Commensurate for age of vehicle but has wear and tear | **N/S** | Not secure |
| **Repair** | Requires repair, replacement or refurbishment | **N/W** | Not working |
| **Wetting** | Fluid escaping with the potential to drip | **N/A** | Not Applicable |
| **Leaking** | Fluid escaping and dripping | **N/C** | Not checked |

## Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

**The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal**

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.