Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
9

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
24 November, 2026	Daimler 250 V8	1966	538mi	1A11299BW

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✔					
Glass	✔					
Bodywork	✔					
Paintwork		✔				Older respray, some scratches around doors & boot
Lamps Condition		✔				
Bumper Bars		✔				Few scratches, large dent in LRH overrider
Brightwork	✔					Light tarnishing on headlamps bezels & some pitting
Seals		✔				
Convertible Roof					✔	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area		✔				
Seats & Belts		✔				Some wear in keeping with age
Floor Coverings		✔				Newer floor carpets don't match rest
Headlining/Visors		✔				
Trim		✔				
Doors		✔				
Windows and Mirrors		✔				
Heating and Ventilation			✔			
Lights/Wipers/Washers/Horn			✔			
Other Electrical		✔				Horn n/w
Entertainment Equipment					✔	
ABS/SRS					✔	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✔					
Corrosion		✔				
Powertrain		✔				
Exhaust			✔			LH exhaust manifold leaking
Brakes			✔			Handbrake cable fouls on exhaust
Wheels & Tyres	✔					Tyres dated 20-2020
Steering & Suspension		✔				
Fuel System		✔				Hoses showing age
Fluid Leaks	✔					

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Fluid Levels/Condition		✔				Requires a service, needs fresh fuel
Cooling System	✔					Working, runs at 80 degree c.
Power Steering					✔	

Electrical		✔				
Engine Running		✔				
Air Conditioning					✔	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance		✔				Needs fresh fuel but runs well otherwise
Transmission		✔				Selector needs adjustment
Noise and Vibration		✔				
Steering and Suspension		✔				
Braking			✔			Pulls to the right under brakes
Clutch					✔	
Instruments			✔			Tacho n/w, speedo operation erratic

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.