Vehicle Observation Report

Donington AUCTIONS & SALES

Lot No.

Description : 1983 Mercedes-Benz W107 380SL **Colour :** Silver

			PHOTO			PHOTO
Chassis No. / VIN :	WDB 107045-22-025833		Y	**Engine No :**	116962-22-016381	Y
Body No :				**Trans No. :**		
Rego / State :	91272-H	VIC C.P.	Y	**Last Reg Date:**		
Odometer :	335220km		Y	**Fuel level :**	Low	Y

Item	✓ / X	Details	PHOTO
PAINT	✓		
PANEL	✓		
GLASS	✓		
CHROME / TRIM	X	Chrome trim on front bumper pitted	Y
WHEELS / TYRES	X	All wheels marked.	Y
TOOLS	✓		
BUMPERS	X	Rubber inserts damaged on both bumpers.	Y
SOFT / HARD TOP	X	Stain in hard top lining, soft top mechanism jammed.	
INTERIOR	X	Holes in passenger seat.	
BOOT / LOAD AREA	✓		
ENGINE BAY	✓		
LIGHTS	✓		
HORN	✓		
HEATER / A/C	X	A/C not working.	
WIPER / WASHER	✓		
KEYS / SPARES	✓		
BOOKS	✓		
ACCESSORIES	✓	Boot lid spoiler fitted.	
SPARE PARTS	X		
ENGINE RUNS	X	Engine runs but idles high, possible vacuum leak,	
DRIVES	✓		

Additional Comments

Exhaust leak, hole in centre muffler.

INSPECTED BY : **DATE :** 9/11/2026